


Monopoint(4505) Flanged Install with Integral driver




Step 1- J-Boxes, hanger bars and/or mounting brackets are not included. Please purchase.



J-Boxes Recommend
Supplied by others
RACO PN#255 w/Bracket
or RACO PN#256 w/o Bracket
are not included. Please purchase.

Step 2- Attach face plate with threaded collar to junction box with 2 screws. Collar to be face down - towards inside of J-box. Threaded collar to be face up, towards floor, for ceiling thickness <1/2" reverse the direction of the collar". Tighten screws




Step 4- Apply ceiling panels with proper cutout sizes (see drawing). Finish ceiling



Step 5- Thread flange receiver into collar until contact with ceiling.
*Paint ceiling before flange install.

5-Wire Connection

Step 6- Before starting step 7, make sure all electrical connections are working



Step 7- Match j-hook in fixture with grooves in receiver. Push up, turn to left until end of rotation, allow to drop into final position of J-hook. Base should be flush with ceiling. Finish.

RECOMMENDED:
Use included
Safety Cable to connect
lamp assembly to
installed receiver






Monopoint (4505) Plaster Install with Integral driver




Step 1- J-Boxes, hanger bars and/or mounting brackets are not included. Please purchase.



J-Boxes Recommend
Supplied by others
RACO PN#255 w/Bracket
or RACO PN#256 w/o Bracket
re not included. Please purchase.

Step 2- Attach face plate with threaded collar to junction box with 2 screws. Collar to be face down - towards inside of J-box. Threaded collar to be face up, towards floor, for ceiling thickness <1/2" reverse the direction of the collar". Tighten screws



Step 4- Apply ceiling panels with proper cutout sizes (see drawing). Finish ceiling



Step 5- Thread receiver into collar until contact with ceiling.



Step 6- Before starting step 7, make sure all electrical connections are working



Step 7- Match j-hook in fixture with grooves in receiver. Push up, turn to left to latch. Base should be flush with ceiling. Finish.


RECOMMENDED:
Use included
Safety Cable to connect
lamp assembly to
installed receiver






Monopoint(4505) Millwork Install with Integral driver





Step 2- Attach face plate with threaded collar to junction box with 2 screws. Collar to be face down - towards inside of J-box. Threaded collar to be face <1/2" reverse the direction of the col-

Step 1- J-Boxes, hanger bars and/or mounting brackets are not included. Please purchase. Jar". Tighten screws



from face (bottom) of joist. Fully thread receiver into collar plate.

Step 4 and Step 5 - Cut millwork (see cutout sizes above) before installing as ceiling. Adjust (back out) receiver so contact is made with millwork cutout when installing panel. Verify that the cutout is centered relative to the receiver.





Step 6 and Step 7- Make sure all electrical connections are working before attempting to install Monopoint into ceiling. Match j-hook in fixture with grooves in receiver. Push up, turn to left to latch. Base should be flush with ceiling. Finish.

RECOMMENDED: Use included Safety Cable to connect lamp assembly to installed receiver






Monopoint(4505) Flanged Receiver Install with Remote Driver




Step 1- All parts are included from flanged receiver to lamp assembly with safety cable.



Step 2- Cut hole in ceiling to specified size above. Paint ceiling before installing wing spring receiver.



hole in ceiling. Wing springs can be bent to fit through cutout.



Step 4- Wing springs should catch into ceiling.



Step 5- Make sure all electrical connections are working



Step 6- Match J-hook in fixture with grooves in receiver. Push up, turn to left to latch. Base should be flush with ceiling. Finish.






Monopoint(4505) Plaster Install with Remote Driver



Step 1- All parts are included from plaster receiver to lamp assembly with safety cable.




Step 2- Cut hole in ceiling to specified size above.



Step 3- Fit plaster flange through hole in ceiling



Step 4- Tighten (2) screws to adjust wing clamps to fit tight with ceiling and flange.



Step 5- Plaster and paint flange. Before starting step 6, make sure all electrical connections are working



Step 6- Match J-hook in fixture with grooves in receiver. Push up, turn to left to latch. Base should be flush with ceiling. Finish.

RECOMMENDED:
Use included
Safety Cable to connect
lamp assembly to
installed receiver







Monopoint(4505) Millwork Install with remote driver



Step 1- J-Boxes, hanger bars and/or mounting brackets are not included. Please purchase.



Step 2- Attach face plate with threaded collar to junction box with 2 screws. Collar to be face down - towards inside of J-box. Threaded collar to be face up, towards floor, for ceiling thickness <1/2" reverse the direction of the collar". Tighten screws




Step 3- Attach hanger bar with J-box assembly to ceiling joist. Assure surface of face plate has 1/2" offset from face (bottom) of joist. Collar can be reversed to accomodate additional ceiling thickness. Install threaded receiver after collar plate has been installed.

CEILING JOIST



Step 6 and Step 7- Make sure all electrical connections are working before attempting to install Monopoint into ceiling. Match j-hook in fixture with grooves in receiver. Push up, turn to left to latch. Base should be flush with ceiling. Finish.



Step 4 and Step 5 - Cut millwork (see cutout sizes above) before installing as ceiling. Adjust receiver so contact is made with millwork cutout when installing panel. Verify that the cutout is centered relative to the receiver.

RECOMMENDED:
Use included
Safety Cable to connect
lamp assembly to
installed receiver




G

Monopoint(4505) Pancake Mount with Remote Driver



Step 1- Attach Pancake Box to structure Run wires through pancake box (Note: must be home run from remote driver)



Step 2- Cut pancake size hole in GWB prior to installation.



Step 3- (2) #8 anodized screws are included for Step 6.



Step 4- Mount GWB over pancake box and prep/finish ceiling.



Step 5- Make electrical connection – assure red to red (+) and black to black (-) . Test electrical.



Step 6- Screw canopy plate to pancake box with (2) #8 screws

ROW 3

A20 Blue

A15 Violet 3D

A16 Turquoise

A18 Light Blue

A21 Navy Blue

A19 Aqua Marine



Step 7- Repeat steps for other Monopoint fixtures



ROW 1
A1 Black
A2 Lime Green
A4 Green
A6 Forrest Green
A7 Olive Drab
A8 Pink

ROW 2
A9 Berry
A10 Dark Pink
A11 Purple
A12 Lavender
A13 Raspberry
A14 Violet

ROW 4 A22 Peach A24 Brown A26 Gold A28 Orange A30 Red A32 Clear A14 Violet

ROW 5

A34 Grey

A34 Grey A36 Antique

NOTE-We can accommodate all anodized finishes with matching screws including standard painted White (P14).

